Oil Field Environmental Incident Summary

Responsible Party: WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: LINDVIG 11-13

Field Name: LONESOME Well File #: 16542

Date Incident:1/18/2016Time Incident:15:30Facility ID Number:County:MCKENZIETwp:151Rng:102Sec:13Qtr:

Location Description: A light mist to the northwest of the facility near the flare pit. Impacted area is

approximately 15' x 60'.

Submitted By: Daniel Ryan Received By:

Contact Person: Daniel Ryan

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:0.3 MileDistance Nearest Water Well:0.3 Mile

Type of Incident: Treater Popoff

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
30 Gallons 30 gallons

Oil 30 Gallons

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 2/11/2016 Clean Up Concluded: 2/11/2016

Risk Evaluation:

None noted.

Areal Extent:

Off location in an area of 15' x 60' to the NW of the flare.

Potential Environmental Impacts:

To be determined.

Action Taken or Planned:

The treater fluid was routed to the tanks to drop treater fluid level. The area was walked to determine impacted area and crews are already in process of scooping up impacted material.

Wastes Disposal Location: An approved location.

Agencies Involved:

Updates

Date: 1/19/2016 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater popoff, was not contained to the facility site. Further followup needed.

Date: 1/21/2016 Status: Inspection Author: Cooper, Mike

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 2:00 p.m. Temp 18 degrees F, wind 0-5 mph. Walked entire perimeter of site. Did not see any evidence of containination off site. Could not locate spill due to the snow cover (4-5 inches). Further follow-up is necessary to check on contamination off site. Tried contacting Daniel Ryan - no answer, no response.